

## 4.5 Software

Pressco Technology Inc.  
Cleveland, Ohio, U.S.A.



29200 Aurora Road  
Cleveland, Ohio  
USA 44139-1847  
TEL (440) 498-2600  
FAX (440) 498-9679  
www.pressco.com

Enclosed is a CD with the latest **INTELLISPEC™** and **INTELLITRAINER™** software, Version 4.5. A list of features and improvements introduced in this version is included in this memo, and upgrade installation instructions are attached.

If you have any questions or need assistance, please do not hesitate to contact our Customer Service Department at (440) 498-2000.

Best regards,

A handwritten signature in black ink that reads 'Fritz Awig'.

Fritz Awig  
Vice President, Customer Support Engineering  
Pressco Technology Inc.

**4.5 SOFTWARE**



## INTELLISPEC Version 4.5 Software

Category	Feature	Description
New Inspection	Distribution Inspection	Mix Label Inspection <b>Benefits:</b> <ul style="list-style-type: none"> <li>• Detect incorrect or misprinted labels and remove them from the product stream.</li> <li>• Applicable to 2 piece cans, plastic &amp; metal closures, crowns, etc.</li> </ul>
Algorithm Enhancement	Code Finder	Improves recognition capabilities of the Alpha-Numeric Correlation inspection <b>Benefits:</b> <ul style="list-style-type: none"> <li>• Allows additional printing or other markings in proximity to the Mold ID number to be ignored</li> <li>• Expands the range of parts that can be inspected</li> </ul>
System Enhancement	Private Counters	A separate set of OPC counters are now available <b>Benefits:</b> <ul style="list-style-type: none"> <li>• Eases long-term statistics tracking</li> <li>• Unaffected when statistics are cleared either manually or automatically</li> <li>• Independent of existing display and reports counters</li> </ul>
New Feature	Molder Graphic	New full-screen color graphic <b>Benefits:</b> <ul style="list-style-type: none"> <li>• Ability to quickly spot problems in a particular area of the blow molder</li> <li>• Track total or last-n defects</li> </ul>
Hardware	System Requirements	<ul style="list-style-type: none"> <li>• <b>Quad-core processor</b></li> <li>• <b>4 gigabytes RAM</b></li> </ul>


**4.5 SOFTWARE**



# Upgrading *INTELLISPEC* Software


You must be an Administrator to upgrade the system.

1. Download the upgrade file.
2. Unzip the file to a temp directory on your PC and burn a CD with all the unzipped files.



All the files shown in the right panel above should be burned onto a CD.  
Important: Burn the CD with the contents in the root directory.

3. Take the CD to the Intellispec to be upgraded. Make sure the Intellispec is operating, and offline. Log in as Administrator or higher.



4. Click the Miscellaneous toolbar button
5. Select the Utilities tab
6. Click the Software Upgrade button
7. Insert the upgrade CD and click the Yes button to start the Setup program.
8. Click the Next button and follow the prompts as the upgrade proceeds.
9. Near the end of the upgrade process, there may be a rather serious-looking message mentioning *logo verification*. Click the Continue Anyway button.
10. When the reboot prompt appears, click OK to restart but *do not remove the CD* until Windows shuts down.
11. The system will restart and run with the new version of software.
12. Some software upgrades require updating your software license key. If your upgrade won't run for this or any other reason, please contact Pressco Technical Support.